



## STRUCTURE EXPLORATIONS




Central support

- Adequate legroom
- Problematic cantilever
- Somewhat elegant




Side supports

- Central support lacking
- Design issue/opacity
- Awkward seating




Edge supports

- Central support lacking
- Design issue/opacity
- Cantilever/central support issues




Numerous metal rod supports

- Child safety issue between bars
- Design/elegance
- Foundations, maintaining the components straight on the site



Specific metal rod supports

- Design/elegance
- Foundations, maintaining the components straight on the site



Spine support

- Elegant
- Adequate legroom
- Possible cantilever problematics